

## **MATERIAL SAFETY DATA SHEET**



Fairprene Industrial Products Company, Inc. 85 Mill Plain Rd., Fairfield, Connecticut 06430

		·			PEGID JUL	0 2 1987		
	PROD	UCT IDE	NTIFICATIO	ON	Dow 1	535		
Product Name: Fairpren	oduct Name: Fairprene NC-6088					azard Rating		
Chemical Name: Neoprene	Coated Co	tton	4 =	Extrem	• —	Fire 0  Health 1 Reactivity		
Official and Mana	roprene/Co	tton	2 =	High Modera		pecific 0		
Synonyms: None CAS# Mixture				Slight Insigni	ficant			
				E	Emergency Telephone (203) 259-3351	No.		
HAZAR	DOUS INGR	EDIENTS	/IDENTITY	INFO	RMATION			
HAZARDOUS COMPONENTS	ACGIH TLV	OSHA PEL	OTHER LIMITS	3 %	HAZARD			
Hydrotreated Heavy								
Napthenic Distillate	5.0 mg/m3			2.8		<del></del>		
			-					
		· · · · · · · · · · · · · · · · · · ·		+		<del></del>		
				1 1				
•	1							
	PHYSICAL A	ND CHE	MICAL PRO	PERT	IES			
Boiling Point ( F.)		N/A	Specific Gravity	(H <sub>2</sub> O = 1)	<u> </u>	1.14		
			Percent, Volatile			4		
Vapor Pressure (mm. Hg.)		N/A	By Volume (%)			N/A		
Vapor Density (Air = 1)			Evaporation Rate (Butyl Acetate =		·	N/A		
Solubility in Water			Melting Point			N/A N/A Rubber" odor		
Appearance and Odor Black,	flexible u			ated	cotton - "Rubb	er" odor		
	FIRE AND	EXPLOSIC	ON HAZAR	D DAT	A			
			Flammable Limit in Air % by Vol.	is				
	N/A	1	III All % by Vol.		Upper N/A			
Extinguishing Media: Water	fog, foam,	. co2. d	ry chemic	al				
Special Fire Fighting Procedures:	Recommend	self-co	ntained b	reath	ing apparatus	<del></del>		
Unusual Fire and Explosion Hazards: _	None							
		•			. 4.			
	_ <del></del>	<del></del>						

This information relates to the specific material designated and may not be valid for such material used in combination with any other materials or in any process. Such information is to the best of our knowledge and belief, accurate and reliable as of the date compiled; however, no representation, warranty or guarantee is made as to its accuracy, reliability or completeness. It is the user's responsibility to satisfy himself as to the suitability and completeness of such information for his own particular use. We do not accept liability for any loss or damage that may occur from the use of this information nor do we offer warranty against patent infringement.

NO'  No ef	known	Skin? N	/A		Ingestion? OSHA Regul	N/A ated?	0
NO et	known	N ARC Monogra	aohs?			ated?	0
NO'  No ei	ffects ex	ARC Monogra	aohs?	0	OSHA Reguli	ated?	0
NO'  No ei	ffects ex		aphs? N	0	OSHA Regul	ated? N	0
No ei	ffects ex		aphs? N	0	OSHA Regul	ated? N	0
No ei	ffects ex		aphs? N	0	OSHA Regul	ated? N	0
No ei	ffects ex		aphs? N	0	OSHA Regul	ated? N	0
None		pected		<u> </u>			
None		pected		· · ·			·
None		pecced		<u>.</u>	<u> </u>		
	Known			<u>, , , , , , , , , , , , , , , , , , , </u>			
	Known		<u></u>				
None						<u> </u>	
None							
None							<u> </u>
	_						
	REACTIV	ITY DATA	A .				
<del></del>	Conditions to	·	<del>-</del>	-	<del></del>		<del></del>
XX ,		•			<del></del>	· · · · · · · · · · · · · · · · · · ·	
				· ·			<del></del>
HCL, oxi	des of n	<u>itrogen</u>	and c	arbon w	hen bu	rning	
	Conditions to	Avoid	<del></del>				
r XX		· .					
SPILL, L	EAK, AND	WASTE (	DISPOS	AL			
leased or spilled	1: N/A		<del></del>				
		-	· · · · · · · · · · · · · · · · · · ·	<del></del>	<u> </u>		
se of in	accorder	ace with	Feder		ato and	l Loca	<u> </u>
						1 DOCA.	<u>-</u>
·			· · · · · · · · · · · · · · · · · · ·				
<u> </u>					<del></del>		
C	ONTROL	MEASUR	ES				
_None							
Vog who	n aurina		Special				
	n curing						
	lasses				<del></del>		
SF	PECIAL PRI	ECAUTIC	)NS				
					- DO 11/	) m L	- 4 h
d Storing: <u>US</u> : o 1 o n a ed	skin cont	act. T	wnen (	orough	אַ טע אַנ <u>.</u>	orea	atn_
<u></u>				ugli	<u>~ J •</u>		
			<del></del>				
	HCL, oxi	CONTROL I  Yes when curing safety glasses  SPECIAL PRI  d Storing: Use local experiments and services are serviced as a serviced at the services are serviced as a serviced as a serviced at the serviced at t	Conditions to Avoid  XX  SPILL, LEAK, AND WASTE I  leased or spilled: N/A  Disc of in accordance with ations.  CONTROL MEASUR  None  Yes when curing leneral)  safety glasses  SPECIAL PRECAUTIO  d Storing: Use local exhaust	Conditions to Avoid  XX  SPILL, LEAK, AND WASTE DISPOS  leased or spilled: N/A  See of in accordance with Feder  ations.  CONTROL MEASURES  None  Yes when curing Special  leneral) Special  seneral Other  safety glasses  SPECIAL PRECAUTIONS  d Storing: Use local exhaust when or	Conditions to Avoid  XX  SPILL, LEAK, AND WASTE DISPOSAL  leased or spilled: N/A  Dispose of in accordance with Federal, Stations.  CONTROL MEASURES  None  Yes when curing Special Other safety glasses  SPECIAL PRECAUTIONS  d Storing: Use local exhaust when curing.	Conditions to Avoid  XX  SPILL, LEAK, AND WASTE DISPOSAL  leased or spilled: N/A  Dispose of in accordance with Federal, State and actions.  CONTROL MEASURES  Wone  Yes when curing Special leneral) Special Other  safety glasses  SPECIAL PRECAUTIONS  d Storing: Use local exhaust when curing. DO NO	Conditions to Avoid  XX  SPILL, LEAK, AND WASTE DISPOSAL  leased or spilled:  N/A  See of in accordance with Federal, State and Local ations.  CONTROL MEASURES  None  Yes when curing Special ceneral) Other  safety glasses  SPECIAL PRECAUTIONS  d Storing: Use local exhaust when curing. DO NOT brea